

# General Environmental Incident Summary

**Incident:** 1778      **Notice:** 8/6/2012      0930      **Occurred:** 8/4/2012      1200

**DEM Incident No:**

**No Further Action:** ☒

**Responsible Party:** Dakota 5 Trucking

**County:** Burleigh

**Twp Rng Sec Qtr:** 138   79   17

**Lat Long + Method:** 46.76687      -100.68440      Calculated

**Location Description:** Parking lot of Elk Industries

**Submitted By Info:** Al Hunt  
NDDoH Response Team  
918 E Divide Ave  
4th Floor  
Bismarck ND 58501-1947

**Received By Info:**

**Contact Info:** Dean Hapfauf  
6749 Sterling Dr  
Bismarck ND 58504

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:** 50 Feet

**Type of Incident:** Truck Draining

**Release Contained:**

**Reported to NRC:** Unknown

**Contaminant:** Produced Water

**Volume of Release:**

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely**

**Hazardous Substance:** Unknown

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

Produced Water was released, when driver opened valve to make sure tank was empty, to move tank to location across parking lot of Elk Industries

**Risk Evaluation:**

**Potential Env. Impacts:**

Parking lot soil

**Action Taken/Planned:**

Soils to be tested to locate extent of spill

**Wastes Disposal Location:**

Bismarck Landfill

**Other Agencies Involved:**

## **Updates**

---

**Date:** 8/6/2012      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Notes:**

Assigned to Al Hunt for inspection and follow-up.

**Updated Volume:** None at the time of this update

---

**Date:** 8/6/2012      **Status:** Inspection

**Author:** Hunt, Al

**Notes:**

Walked parking lot. Talked with land owner on 8-6-2012. Truck owner and leasor of lot was called at 14:30. Communicated that cleanup was required. Gave him cleanup requirements and testing procedures. Samples taken on 8-8-2012.

**Updated Volume:** None at the time of this update

---

**Date:** 10/2/2018      **Status:** Reviewed - No Action Required

**Author:** Martin, Russell

**Notes:**

Reviewed photos and sample results. Spill contained on dirt lot of trucking company. Aerial imagery show no offsite impact. Corrected lat/long based on address and incident photos. No further follow-up required at this time.

**Updated Volume:** None at the time of this update